Single Point Threading Guide

	Pass 1	Pass 2	Pass 3	Pass 4	Pass 5	Pass 6	Pass 7	Pass 8	Pass 9	Pass 10	Pass 11	Pass 12	Pass 13	Pass14	Total Cut	Passes
TPI																
10	.0234	.0331	.0405	.0468	.0523	.0573	.0619	.0661	.0702	.0740	.0776	.0810	.0843	.0875	.0875	14
11	.0221	.0312	.0382	.0441	.0493	.0540	.0584	.0624	.0662	.0698	.0732	.0764	.0795		.0795	13
12	.0210	.0298	.0365	.0421	.0471	.0516	.0557	.0595	.0631	.0666	.0698	.0729			.0729	12
13	.0203	.0287	.0352	.0406	.0454	.0497	.0537	.0574	.0609	.0642	.0673				.0673	11
14	.0198	.0280	.0342	.0395	.0442	.0484	.0523	.0559	.0593	.0625					.0625	10
16	.0182	.0258	.0316	.0365	.0408	.0447	.0482	.0516	.0547						.0547	9
18	.0172	.0243	.0298	.0344	.0384	.0421	.0455	.0486							.0486	8
20	.0165	.0234	.0286	.0331	.0370	.0405	.0438								.0438	7
24	.0149	.0210	.0258	.0298	.0333	.0365									.0365	6
28	.0140	.0198	.0242	.0280	.0313										.0313	5
32	.0122	.0173	.0212	.0245	.0273										.0273	5
36	.0122	.0172	.0210	.0243											.0243	4
40	.0109	.0155	.0189	.0219											.0219	4
44	.0099	.0141	.0172	.0199											.0199	4
48	.0105	.0149	.0182												.0182	3
56	.0090	.0128	.0156												.0156	3
64	.0079	.0112	.0137												.0137	3
72	.0086	.0122													.0122	2
80	.0077	.0109													.0109	2

NOTE: All readings are cumulative and are 60° infeeds read on the compound micrometer collar.